

GPS™ FAQs


Why am I having trouble fitting the clear nylon liner into the metal housing?

If you are having difficulty inserting the clear component into the metal housing, it is likely you have accidentally picked up the clear comfort cap instead.

How can I tell the difference between the nylon liner and the comfort cap?

There are several design differences between these components that are easy to spot once you are aware of them. The nylon liner has a retentive groove near the top, while the edges of the comfort cap are simply rounded. Inside the nylon liner are a small hole and two retentive slots that aid in the removal and replacement of worn liners. The inside of the comfort cap is smooth.

GPS™ Nylon Liner



Comfort Cap

